

# PUTTING THE 'ABLE' IN CLEANABLE

IPAC-CSO EDUCATION DAY

APRIL 12, 2018

PRESENTED BY

WENDY JAMES, RN, BSCN, MHS, CIC



I have no conflict of interest to declare.

#### **DECLARATION**

The goal of this presentation is to highlight practical challenges in achieving best practice cleaning standards in a health care setting. It is not intended to endorse or denounce any particular cleaning or disinfection product or method.

# WARNING





Santé publique Ontario • PIDAC (2012/2018)

#### EASE OF MAINTENANCE AND REPAIR

- DURABLE, EASY TO MAINTAIN/REPAIR
- FABRIC TEARS, SCRATCHES OR CHIPPED SURFACES ALLOWS FOR ENTRY/ACCUMULATION OF ORGANISMS
- ITEM CANNOT BE PROPERLY CLEANED





- PIDAC (2012/2018)
  - EASE OF MAINTENANCE AND REPAIR
  - CLEANABLE
    - FLUID RESISTANT, NON-POROUS
    - ABLE TO WITHSTAND REPEATED CLEANING
    - COMPATIBLE WITH HOSPITAL-GRADE DISINFECTANTS





- PIDAC (2012/2018)
  - EASE OF MAINTENANCE AND REPAIR
  - CLEANABLE
  - RESISTANT TO MICROBIAL GROWTH
    - METALS, HARD PLASTICS
    - MATERIALS THAT DO NOT HOLD MOISTURE
    - AVOID WET ORGANIC SUBSTRATES (WOOD)





- PIDAC (2012/2018)
  - EASE OF MAINTENANCE AND REPAIR
  - CLEANABLE
  - RESISTANT TO MICROBIAL GROWTH
  - NONPOROUS
    - POROUS UPHOLSTERED FURNITURE SHOULD ON NOT BE USED IN PATIENT CARE AREAS





- PIDAC (2012/2018)
  - EASE OF MAINTENANCE AND REPAIR
  - CLEANABLE
  - RESISTANT TO MICROBIAL GROWTH
  - NONPOROUS
  - SEAMLESS
    - SEAMS CAN HARBOUR BACTERIA & ARE DIFFICULT TO CLEAN




# 'If you can't clean it, don't buy it'

PIDAC,2018



#### THE CYCLE

- FLUCTUATING HOSPITAL-ACQUIRED RATES OF MRSA, VRE, AND C. DIFF
  - CLEANING WOULD BE STEPPED UP, IN ADDITION TO OTHER MEASURES, IN IMMEDIATE RESPONSE TO HAI CONCERNS
    - RESULTED IN SHORTER-TERM
       IMPROVEMENT





- CAN PERSIST FOR EXTENDED PERIODS OF TIME
- INCREASE LIKELIHOOD OF TRANSMISSION







#### 62 specimens were sent

- 4 controls (2 MRSA, 2 C. diff)
  - Cloths were randomly bagged as controls to monitor for inadvertent contamination of supply during specimen collection
- 29 for MRSA
- 29 for C. diff



#### 62 specimens were sent

- 4 controls (2 MRSA, 2 C. diff)
  - Cloths were randomly bagged as controls to monitor for inadvertent contamination of supply during specimen collection
- 29 for MRSA
- 29 for C. diff




62 specimens were sent

- 4 controls (2 MRSA, 2 C. diff)
  - Cloths were randomly bagged as controls to monitor for inadvertent contamination of supply during specimen collection
- 29 for MRSA
- 29 for C. diff



#### **SIDEBAR**


The chair was immediately removed from service. Its now resting in pieces.





#### **SIDEBAR**

The chair was immediately removed from service. Its now resting in pieces.






- 3 SPECIMENS POSITIVE FOR MRSA
  - CORK BOARD IN A PATIENT ROOM
  - WOODEN HANDLED CHAIR IN A KNOWN MRSA ROOM
    - BEDRIDDEN PATIENT
    - CHAIR APPROX. 1 METRE FROM THE END OF THE PATIENT'S BED
  - FABRIC CHAIR IN NURSING STATION
     CONFERENCE ROOM



- 3 SPECIMENS POSITIVE FOR MRSA
  - CORK BOARD IN A PATIENT ROOM
  - WOODEN HANDLED CHAIR IN A KNOWN MRSA ROOM
    - BEDRIDDEN PATIENT
    - CHAIR APPROX. 1 METRE FROM THE END OF THE PATIENT'S BED
  - FABRIC CHAIR IN NURSING STATION
     CONFERENCE ROOM




- 3 SPECIMENS POSITIVE FOR MRSA
  - CORK BOARD IN A PATIENT ROOM
  - WOODEN HANDLED CHAIR IN A KNOWN MRSA ROOM
    - BEDRIDDEN PATIENT
    - CHAIR APPROX. 1 METRE FROM THE END OF THE PATIENT'S BED
  - FABRIC CHAIR IN NURSING STATION
     CONFERENCE ROOM





- 3 SPECIMENS POSITIVE FOR C. DIFF
  - RIBOTYPES 020, 027, 014
  - SAME FABRIC CHAIR IN NURSING
     STATION CONFERENCE ROOM
  - WOODEN TABLE IN PAEDIATRICS
  - PHYSIO TRANSFER BOARD







- ON THE C. DIFF PLATES:
  - 2/29 SPECIMENS WERE POSITIVE FOR ANAEROBIC SPORE-FORMING BACTERIA
  - BOTH FROM WOODEN ROCKING CHAIRS
    - PAEDS
    - FAMILY BIRTHING UNIT





- ON THE C. DIFF PLATES:
  - 2/29 SPECIMENS WERE POSITIVE FOR ANAEROBIC SPORE-FORMING BACTERIA
  - BOTH FROM WOODEN ROCKING CHAIRS
    - PAEDS
    - FAMILY BIRTHING UNIT







- ON THE MRSA PLATES:
  - 25/29 SPECIMENS WERE POSITIVE FOR OTHER ORGANISMS
  - AS MANY AS 5 COLONY TYPES FROM ONE SPECIMEN
    - FABRIC DESK CHAIR FROM HALLWAY DOCUMENTATION STATION
    - VINYL DESK CHAIR AT NURSES' STATION








Bacillus/Enterococcus sp., Coag-neg. Staph, +?



Bacillus/Enterococcus sp.



Micrococcus sp., Bacillus/Enterococcus sp.



Bacillus/Enterococcus sp., Coag-neg. Staph, +?



Bacillus/Enterococcus sp.



Micrococcus sp., Bacillus/Enterococcus sp.






#### **ELECTRONICS**

- MINIMALLY INVASIVE (HYBRID) VASCULAR OR
  - BANK OF 4 LCD SCREENS THAT SITS WITHIN ABOUT 1/2 METRE OF THE PATIENT
- LCD SCREENS WERE SHOWING SIGNS OF DAMAGE
  - RISK TO PATIENT SAFETY FROM LACK OF ACUITY IN VISUALIZING ANATOMICAL IMAGES
  - RISK TO PATIENT SAFETY FROM NOT PROPERLY DISINFECTING
     SCREENS



#### "CLEAN ONLY WITH STERILE WATER"





- ATP MONITOR REVIEW
  - MEASURES "ADENOSINE TRIPHOSPHATE (ATP)
    BIOLUMINESCENCE"
    - MEASURED USING AN ENZYME REACTION WHICH OCCURS NATURALLY IN THE TAIL OF FIREFLIES ("FIREFLY TECHNOLOGY")
    - LUMINOMETER MEASURES THE AMOUNT OF LIGHT PRODUCED
    - AMOUNT OF LIGHT IS PROPORTIONAL TO THE AMOUNT OF ATP PRESENT

Hybrid OR	
Bank of 4 LCD screens	
Top left	2041
Top right	425
Bottom left	469
Bottom right	14135
PACS monitor right	312
PACS monitor left	39
Table Controls (screen)	549

Hybrid OR		
Bank of 4 LCD screens		
Top left	2041	
Top right	425	
Bottom left	469	
Bottom right	14135	
PACS monitor right	312	
PACS monitor left	39	
Table Controls (screen)	549	
Toilet seat (public washroom)	176	


Hybrid OR		
Bank of 4 LCD screens		
Top left	2041	38
Top right	425	13
Bottom left	469	0
Bottom right	14135	*554
PACS monitor right	312	0
PACS monitor left	39	0
Table Controls (screen)	549	**3210
Toilet seat (public washroom)	176	

Hybrid OR		
Bank of 4 LCD screens		
Bottom right	14135	*554
Toilet seat (public washroom)	176	

Hybrid OR		
Table Controls (screen)	549	**3210
Toilet seat (public washroom)	176	

ONCE WE GET ITEMS/EQUIPMENT THAT CAN BE CLEANED, WHAT DO WE CLEAN THEM **MILH**<sup>5</sup>





FOLLOW THE MANUFACTURERS' INSTRUCTIONS!



# PUTTING THE ABLE IN CLEANABLE

CHALLENGES

#### **INAPPROPRIATE CLEANING INSTRUCTIONS:**

- "INCOMPATIBLE WITH MOST HOSPITAL-GRADE DISINFECTANTS"
  - PIECE OF EQUIPMENT TO BE USED IN THE OR!
- Sbust arcohor (\$\$\$\$\$)
- CONCENTRATION OF BLEACH NOT COMMERCIALLY AVAILABLE AS PREPARED WIPE
- SOLUTIONS RANGING FROM PHENOLICS TO STERILE WATER FOR THE SAME PIECE OF EQUIPMENT BUT NOTHING PRACTICAL
- USE LCD WIPE ONLY (ELECTRONIC TOUCH SCREENS)

#### PUTTING THE ABLE IN CLEANABLE CHALLENGES

- PRACTICAL ISSUES WITH MULTIPLE BRANDS OF DISINFECTANT WIPES/CLEANING PRODUCTS
  - STORAGE
  - AVAILABILITY/CONVENIENCE
  - CORRECT USE/APPLICATION
- NO GUARANTEES THAT THE CORRECT PRODUCT WILL BE USED ON A PARTICULAR PIECE OF EQUIPMENT



- CHECK WITH EQUIPMENT MANUFACTURER
  - HAS THE CLEANING PRODUCT(S) YOUR ORGANIZATION USES BEEN TESTED ON THEIR EQUIPMENT?
- WORK WITH CLEANING PRODUCT COMPANY
  - MAY BE ABLE TO APPROACH MANUFACTURER TO DO TESTING
  - MAY HAVE ALREADY TESTED THEIR CLEANING PRODUCT ON THE SAME OR SIMILAR SURFACE MATERIAL AS THE EQUIPMENT BEING PURCHASED



## PUTTING THE ABLE IN CLEANABLE

- REQUIRES COLLABORATION
   AND TEAMWORK BETWEEN
   STAKEHOLDERS TO ENSURE
   THAT WE PROVIDE SAFE,
   CLEANABLE HEALTHCARE
- WE'RE IN THIS TOGETHER!

